

GENWAL COAL COMPANY

RECEIVED

FEB 10 1992

DIVISION OF
OIL GAS & MINING

February 2, 1992

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West, North Temple
Salt Lake City, Utah 84180-1203

RE: Permit # ACT 015-032
Genwal Coal Company
Violation 91-15-2-3
Surface Map

Dear Mr. Haddock:

Due to weather conditions that have existed from 11/07/91 until 02/02/92 Genwal Coal Company has not been able to conduct a ground survey to verify plate 3-1 as required by Violation 91-15-2-3.

Genwal Coal Company requests a second extension to violation 91-15-2-3 until 04/15/92. The extension would allow for the snow to melt exposing the ground which would allow for an accurate survey to be performed.

Genwal is anxious to complete the survey and will notify the Division at the first opportunity to survey.

If you have any questions or comments please call.

Sincerely;

R. Jay Marshall
R. Jay Marshall P.E.
Chief Engineer
Genwal Coal Company